



# CAR RELEASE CONDITION FORM

For Non-UTC Shops

Form: FOS-026-1

Mark / Number: ACFX73711 Repair Shop: GIBW Location: Neodesha Ks

\*Gasket Applied : Gylon 3510  
Additional Gasket: FDA - EPDM  
Gasket Manufacturer: USP & Eagle Gaskets - Midland

\*O-ring Applied: FDA - EPDM

**\*Car Interior Clean:**

- Compartment 1:  Clean Level A - Clean  Clean Level B - Safe for tank entry/minor residue  Not Clean  
 Car not Opened
- Compartment 2:  Clean Level A - Clean  Clean Level B - Safe for tank entry/minor residue  Not Clean  
 Car not Opened
- Compartment 3:  Clean Level A - Clean  Clean Level B - Safe for tank entry/minor residue  Not Clean  
 Car not Opened
- Compartment 4:  Clean Level A - Clean  Clean Level B - Safe for tank entry/minor residue  Not Clean  
 Car not Opened

**\*Coating Rating OR Lining Condition OR Interior Condition is required. Comments optional.**

- Coating Rating:  C0 - N/A  
 C6 - Coating loss greater than 8 Sq ft  
 C7 - Coating loss between 3 and 8 Sq ft  
 C8 - Coating loss between 1 and 3 Sq ft  
 C9 - Coating loss between 0 and 1 Sq ft  
 C10 - No faults/defects

Lining Condition:  Good Order Rubber  Bad Order Rubber  New Rubber

**Interior Condition:**

- Compartment 1:  Brush Blast  Commercial Blast  White Metal Blast  Film  Stain  
 Light Rust  Medium Rust  Heavy Rust
- Compartment 2:  Brush Blast  Commercial Blast  White Metal Blast  Film  Stain  
 Light Rust  Medium Rust  Heavy Rust
- Compartment 3:  Brush Blast  Commercial Blast  White Metal Blast  Film  Stain  
 Light Rust  Medium Rust  Heavy Rust
- Compartment 4:  Brush Blast  Commercial Blast  White Metal Blast  Film  Stain  
 Light Rust  Medium Rust  Heavy Rust

Comment: Stainless Steel tank cleaned to Food Grade Requirements

\*Nitrogen Purge Applied? (Y/N) N Purge Oxygen Level: N/A % And/Or Pad PSI: N/A %